


RF1037200

Bon Jour Unplugged Base assembly with new battery kit



WARNING! When installing and whenever acting on the appliance, ensure that the power supply has been switched off. For the installation of the spare-part, it is necessary to consult a qualified electrician.

RF1037200

Bon Jour Unplugged Base assembly with new battery kit




Fig.1




Fig.2

Remove the base assembly with battery kit:
It's necessary to remove the rubber pad (A) from underneath the lamp base.
Unfasten the three fixing screws (B).

WARNING! When installing and whenever acting on the appliance, ensure that the power supply has been switched off.
For the installation of the spare-part, it is necessary to consult a qualified electrician.

RF1037200

Bon Jour Unplugged Base assembly with new battery kit




Fig.3



Fig.4

Remove the damaged base assembly with battery kit (C) from the lamp body (D).

Disconnect the connector (E) using a small clamp from the battery kit.

Assemble now the new spare-part:

Connect the connector (E) to the battery kit (C).

WARNING! When installing and whenever acting on the appliance, ensure that the power supply has been switched off.
For the installation of the spare-part, it is necessary to consult a qualified electrician.

RF1037200

Bon Jour Unplugged Base assembly with new battery kit




Fig.5




Fig.6

Assemble the base the new battery kit (C) to the lamp body (D).

Remarks!!! ensure that the USB port is in correspondence with the opening slot of the lamp body.

Fasten the three fixing screws (B).

WARNING! When installing and whenever acting on the appliance, ensure that the power supply has been switched off.
For the installation of the spare-part, it is necessary to consult a qualified electrician.

RF1037200

Bon Jour Unplugged Base assembly with new battery kit



Fig.7



Fig.8

Apply the new rubber pad (A) underneath the lamp base.

WARNING! When installing and whenever acting on the appliance, ensure that the power supply has been switched off.
For the installation of the spare-part, it is necessary to consult a qualified electrician.